

7425.2100 LIGHTING DEVICES; INCORPORATIONS BY REFERENCE.

Subpart 1. **Incorporations by reference.** Each of the following standards, recommended practices, and regulations are incorporated by reference for the lighting device indicated:

A. auxiliary driving lamp: SAE standard J581a, "Auxiliary Driving Lamps - SAE J581a," revised 1980, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

B. auxiliary low-beam lamp: SAE standard J582 SEP81, "Auxiliary Low Beam Lamp - SAE J582 SEP81," 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

C. auxiliary passing lamp: SAE standard J582, "Electric Supplementary Passing Lamp - SAE J582," SAE Handbook 1973, published by Society of Automotive Engineers, Inc. (New York, NY, 1973);

D. backup lamp: Code of Federal Regulations, title 49, section 571.108;

E. bicycle rear red reflector: SAE standard J594f, "Reflex Reflectors - SAE J594f," revised January 1977, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

F. bicycle side reflector: Code of Federal Regulations, title 16, part 1512 (1983);

G. bicycle reflectorized pedal: Code of Federal Regulations, title 16, part 1512 (1983);

H. bicycle reflectorized tire: Code of Federal Regulations, title 16, part 1512 (1983);

I. clearance lamp: Code of Federal Regulations, title 49, section 571.108;

J. driving lamp: SAE standard J581a, "Auxiliary Driving Lamps - SAE J581a," 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

K. electric emergency lantern: SAE standard J596, "Electric Emergency Lanterns - SAE J596," SAE Handbook 1978, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1978);

L. emergency reflective triangle: Code of Federal Regulations, title 49, section 571.125;

M. flare: SAE standard J597, "Liquid Burning Emergency Flares - SAE J597," SAE Handbook 1978, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1978);

N. flashing warning lamp: SAE standard J595b, "Flashing Warning Lamps for Authorized Emergency, Maintenance and Service Vehicles - SAE J595b," revised July 1964, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

O. fog lamp: SAE standard J583 MAY81, "Front Fog Lamps - SAE J583 MAY81," 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

P. front cornering lamp: SAE recommended practice J852b, "Cornering Lamps - SAE J852b," revised February 1965, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

Q. fusee: Code of Federal Regulations, title 49, section 393.95 (1983);

R. hazard warning signal flasher: Code of Federal Regulations, title 49, section 571.108;

S. hazard warning signal switch: Code of Federal Regulations, title 49, section 571.108;

T. headlamp assembly and optical unit: Code of Federal Regulations, title 49, section 571.108;

U. headlamp beam switching device: Code of Federal Regulations, title 49, section 571.108;

V. identification lamps: Code of Federal Regulations, title 49, section 571.108;

W. license plate lamp: Code of Federal Regulations, title 49, section 571.108;

X. motorcycle auxiliary front lamp: SAE recommended practice J1306 JUN80, "Motorcycle Auxiliary Front Lamps - SAE J1306 JUN80," 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

Y. motorcycle headlamp: Code of Federal Regulations, title 49, section 571.108;

Z. motorcycle turn-signal lamp: Code of Federal Regulations, title 49, section 571.108;

AA. parking lamp: Code of Federal Regulations, title 49, section 571.108;

BB. portable red reflector: SAE recommended practice J774c, "Emergency Warning Device - SAE J774c," revised January 1971, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

CC. rear cornering lamp: SAE recommended practice J1373 JUN82, "Rear Cornering Lamp - SAE J1373 JUN82," 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

DD. rear turn-signal lamp: SAE recommended practice J186a, "Supplemental High Mounted Stop and Rear Turn Signal Lamps - SAE J186a," revised September 1977, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

EE. reflex reflector: Code of Federal Regulations, title 49, section 571.108;

FF. safety glass: Code of Federal Regulations, title 49, section 571.205;

GG. school bus prewarning flashing amber signal lamp: Code of Federal Regulations, title 49, section 571.108;

HH. school bus stop-warning flashing red signal lamp: Code of Federal Regulations, title 49, section 571.108;

II. school bus stop arm: SAE recommended practice J1133a, "School Bus Stop Arm - SAE J1133a," revised November 1977, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

JJ. school bus white strobe lamp: Minnesota Statutes, section 169.64, subdivision 7;

KK. side marker lamp: Code of Federal Regulations, title 49, section 571.108;

LL. side turn-signal lamp: SAE recommended practice J914b, "Side Turn Signal Lamps - SAE J914b," revised July 1978, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

MM. spot lamp: SAE standard J591b, "Spot Lamps - SAE J591b," revised December 1972, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

NN. stop lamp: Code of Federal Regulations, title 49, section 571.108;

OO. supplemental high-mounted stop lamp: Code of Federal Regulations, title 49, section 571.108;

PP. tail or rear-position lamp: Code of Federal Regulations, title 49, section 571.108;

QQ. 360-degree emergency warning signal lamp: SAE recommended practice J845, "360 Deg Emergency Warning Lamp - SAE J845," reaffirmed without change May 1972, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983);

RR. turn-signal flasher: Code of Federal Regulations, title 49, section 571.108;

SS. turn-signal lamp: Code of Federal Regulations, title 49, section 571.108;

TT. turn-signal switch: Code of Federal Regulations, title 49, section 571.108;

UU. turn-signal system: Code of Federal Regulations, title 49, section 571.108;

VV. warning lamp alternating flasher: SAE recommended practice J1054, "Warning Lamp Alternating Flashers - SAE J1054," revised January 1977, 1983 SAE Handbook, published by Society of Automotive Engineers, Inc. (Warrendale, PA, 1983).

Subp. 2. **Availability of SAE standards.** The SAE standards and recommended practices incorporated by reference in subpart 1 are available for inspection and copying at the Hill Reference Library, 80 W. Fourth Street, Saint Paul, Minnesota 55102.

Subp. 3. **Frequency of changes to SAE standards.** The SAE standards and recommended practices incorporated by reference in subpart 1 are not subject to frequent changes.

Statutory Authority: *MS s 169.468; 169.65*

History: *9 SR 1252*

Published Electronically: *May 1, 2000*