

4731.4452 BRACHYTHERAPY SOURCES ACCOUNTABILITY.

A. A licensee must maintain accountability at all times for all brachytherapy sources in storage or use.

B. As soon as possible after removing sources from a patient or human research subject, a licensee must return brachytherapy sources to a secure storage area.

C. A licensee must maintain a record of the brachytherapy source accountability according to part 4731.4512.

Statutory Authority: *MS s 144.1202; 144.1203*

History: *29 SR 755*

Published Electronically: *March 12, 2009*