

7017.1215 QUALITY ASSURANCE AND CONTROL REQUIREMENTS FOR COMS.

For quality assurance and control requirements for COMS, the facility owner or operator must conduct quality assurance and quality control as specified in Procedure 3 - Quality Assurance Requirements for Continuous Opacity Monitoring Systems at Stationary Sources, Code of Federal Regulations, title 40, part 60, Appendix F, as amended, which is adopted and incorporated by reference.

Statutory Authority: *MS s 115.03; 116.07*

History: *41 SR 763*

Published Electronically: *January 27, 2017*