

**7049.0580 POTW MONITORING IN LIEU OF INDUSTRIAL USER SELF-MONITORING.**

Sampling and analysis for baseline monitoring reports as required by parts 7049.0500 to 7049.0550, 90-day compliance reports as required by part 7049.0560, and periodic reports on continued compliance as required by part 7049.0570 may be performed by the control authority in lieu of the industrial user. If the receiving POTW performs the required sampling and analysis in lieu of the industrial user, the industrial user is not required to submit the compliance certification required with baseline monitoring reports under parts 7049.0500 to 7049.0550 and 90-day compliance reports under part 7049.0560. In addition, if the receiving POTW collects all the information required for baseline monitoring reports under parts 7049.0500 to 7049.0550, 90-day compliance reports under part 7049.0560, and periodic reports on continued compliance under part 7049.0570, including flow data, the industrial user is not required to submit the reports.

**Statutory Authority:** *MS s 115.03*

**History:** *33 SR 696*

**Published Electronically:** *November 6, 2008*