

7511.0705 [Repealed, 40 SR 1437]

7511.0705 SECTION 705, DOOR AND WINDOW OPENINGS.

IFC section 705.2 is amended by adding an exception to read:

Exception: Periodic testing and inspection in accordance with NFPA 80 and NFPA 105 is not required for swinging fire door and smoke door assemblies. Swinging fire door and smoke door assemblies shall be maintained in an operable condition in accordance with NFPA 80 and NFPA 105. Damaged or defective swinging fire door and smoke door assemblies shall be repaired or replaced.

Statutory Authority: *MS s 326B.02*

History: *44 SR 610*

Published Electronically: *April 16, 2020*