

**1305.0714** [Repealed, 32 SR 7]

**1305.0714 SECTION 714, PENETRATIONS.**

IBC section 714.4.1.2 is amended by modifying exception 7 as follows:

7. The ceiling membrane of 1- and 2-hour fire-resistance-rated horizontal assemblies is permitted to be interrupted with the double wood top plate of a wall assembly, provided that all penetrating items through the double top plates are protected in accordance with Section 714.4.1.1.1 or 714.4.1.1.2.

**Statutory Authority:** *MS s 326B.02; 326B.101; 326B.106*

**History:** *39 SR 1605*

**Published Electronically:** *June 19, 2015*