

**4658.4540 LAUNDRY AREA; NEW CONSTRUCTION.**

Air in the laundry must be vented away from the finishing and ironing area and toward the extracting and washing area. The general air movement must be from the clean area to the soiled area, and must be of sufficient volume to remove steam, odors, and excessive heat. Dryers must be provided with a lint collector. Horizontal exhaust ducts must exhaust to the outside. The ducts must be provided with access panels for cleaning.

**Statutory Authority:** *MS s 144A.04; 144A.08*

**History:** *21 SR 196*

**Published Electronically:** *October 11, 2007*