

7011.1620 PERFORMANCE TEST METHODS.

Unless another method is approved by the commissioner, any person required to submit performance tests for a sulfuric acid production unit shall utilize the following test methods:

- A. Method 1 for sample and velocity traverses;
- B. Method 2 for velocity and volumetric flow rate;
- C. Method 3 for gas analysis; and
- D. Method 8 for the concentrations of SO₂ and acid mist.

Statutory Authority: *MS s 116.07*

History: *L 1987 c 186 s 15; 18 SR 614*

Published Electronically: *February 25, 2008*