

7011.1910 PERFORMANCE TEST METHODS.

Unless another method is approved by the agency, an owner or operator required to submit performance tests for a brass or bronze ingot production plant must use the following test methods to demonstrate compliance:

- A. Method 1 for sample and velocity traverses;
- B. Method 2 for velocity and volumetric flow rate;
- C. Method 3 for gas analysis;
- D. Method 5 for the concentration of filterable particulate matter and the associated moisture content.

Statutory Authority: *MS s 115.03; 116.07*

History: *18 SR 614; 41 SR 763*

Published Electronically: *January 27, 2017*